

# In-Production Photo Report for Brampton Fire & Emergency Services, ON Job# 44830 : PWO# 34656479


---

Status as of March 27, 2026

In this report your cab was staged, the frame remained staged (no photos), the pump house was painted then continued initial assembly, and the body remained staged (no photos). In the next report your cab, frame, and body may remain staged while the pump house may complete initial assembly.



*For valued customers of*  
**COMMERCIAL**  
EMERGENCY EQUIPMENT CO.



DSC07150



DSC07151




DSC07152



DSC07153



DSC07154



DSC07024



DSC07025



DSC07026



DSC07027



DSC07028



DSC07029



DSC07030



DSC07031