

In-Production Photo Report for Brampton Fire & Emergency Services, ON Job# 44830 : PWO# 34656479

Status as of April 10, 2026

In this report your cab began initial assembly, the frame build continued, the pump house completed initial assembly, and the body began initial assembly. In the next report your cab may continue initial assembly, the frame build may continue, the pump house may be staged, and body may continue initial assembly.



For valued customers of
COMMERCIAL
EMERGENCY EQUIPMENT CO.

SYSTEM FORM	QSF10
Window Sheet	Effective Da
	Page 1
Job #: 44830-1	
9484	
& Emergency Services	
Christina	


DSC07087



DSC07088



DSC07089



DSC07090



DSC07091



DSC07199



DSC07200



DSC07201



DSC07202



DSC07203



DSC07010



DSC07011




DSC07012



DSC07013



DSC07014



DSC07092



DSC07093



DSC07094



DSC07095



DSC07096