


In-Production Photo Report for Brampton Fire & Emergency Services, ON Job# 44831 : PWO# 34656521

Status as of April 03, 2026

In this report your cab, frame and body were staged (no photos) while the pump house continued initial assembly. In the next report your cab may begin initial assembly, the frame build may continue, the pump house may complete initial assembly, and body may remain staged to begin initial assembly.



For valued customers of
COMMERCIAL
EMERGENCY EQUIPMENT CO.



DSC07037



DSC07038



DSC07039




DSC07040



DSC07041



DSC07042



DSC07043